

# PERSPECTA

STEREOPHONIC SOUND

IMPORTANT

September 28, 1954

TECHNICAL BULLETIN NO. 2

PERSPECTA SOUND integrators shipped and installed up to the present time have had the auto-switching sensitivity adjusted so that a steady carrier reading of '50' on any one or more meters, operates the unit in Perspecta Sound condition.

It is recommended that all units be re-adjusted immediately so that a steady carrier reading of '38' on any one or more meters will operate the unit in Perspecta Sound condition.

This re-adjustment is to be made in accordance with the procedure outlined in the manufacturers installation and operating manuals.